

WG19OBX, BMW I3

Registration: WG19OBX

Colour: BLUE

Odometer: 21409

Appraised: 28/04/2021

Condition		
1	Front/Bumper	Poor Previous Repair (Poor paint)
2	Front/Bonnet	Chipped (1 to 5)
3	Nearside/Front/Door	Chipped (Edge chip)
4	Offside/Front/Door	Chipped (Edge chip)
5	Offside/Front/Wheel/Alloy - Painted/20	Scratched (Over 50mm)
6	Offside/Rear/Door	Scratched (Upto 25mm thru paint)
7	Offside/Rear/Quarter Panel/Qtr Panel Moulding	Chipped (1 to 5)
8	General Interior;	Buyer Advisory (Report only)
9	Offside/Rear/Quarter Panel/Qtr Panel	Fall Out (Not through lacquer)



