

**NJ64 HZP, NISSAN LEAF**

Registration: NJ64 HZP

Colour: GREY

Appraised: 11/06/2021

Transmission: Automatic

Odometer: 55,005 miles

**Equipment**

Alloy Wheels


Climate Control

Navigation Media

Navigation System

Privacy Glass

**Exterior condition**



- 1 Bonnet; Chipped; Multiple Chips

---

- 2 Bumper Front; Scratched; Over 100mm Thru Paint

---

- 3 A Post os; Scratched; UpTo 25mm Thru Paint

---

- 4 Bumper Front; Chipped; Multiple Chips

---

- 5 Bumper Rear; Scratched; 25 to 100mm Thru Paint

---

- 6 Door nsf; Scratched; UpTo 25mm Thru Paint

---

- 7 Door nsf; Chipped; Edge Chip

---

- 8 Door nsr; Chipped; Edge Chip

---

- 9 Door osf; Chipped; Edge Chip

---

- 10 Door osr; Chipped; Edge Chip

---

- 11 Qtr Panel nsr; Dented; Between 10mm + 30mm

---

- 12 Wheel nsf; Corroded; Light

---

- 13 Wheel nsr; Scratched; Over 50mm

---

- 14 Wheel osf; Scratched; Over 50mm

---

- 15 Wheel osf; Corroded; Light

---

- 16 Wheel osr; Corroded; Light

---

- 17 Wing osf; Chipped; 1 To 5

18 Bonnet; Scratched; Over 25mm Not Thru Paint

---

19 C Post ns; Scratched; Over 25mm Not Thru Paint

---

20 Door nsf; Scratched; Over 25mm Not Thru Paint

---

21 Door nsr; Scratched; Over 25mm Not Thru Paint

---

22 Door osf; Scratched; Over 25mm Not Thru Paint

---

23 Door osr; Scratched; Over 25mm Not Thru Paint

---

24 Roof; Scratched; Over 25mm Not Thru Paint

---


25 Tailgate; Scratched; Over 25mm Not Thru Paint

---


26 Wing nsf; Scratched; Over 25mm Not Thru Paint

---

Click to enlarge image



## Interior condition



1 Seat Back Cover osf; Scuffed; Over 25mm

---

2 Tailgate Pad; Scuffed; Over 25mm

---

3 Door Pad osf; Soiled; Light

---

4 Door Pad osr; Soiled; Light

---

5 Rear Panel Trim Int; Soiled; Light

---

6 Seat Back Cover nsr; Soiled; Light

---

7 Seat Base Cover nsr; Soiled; Light

---